

LP2307

Oil Pump for Ford 1.0
EcoBoost Models



The 1.0 EcoBoost is known for oil pressure issues as vehicles accumulate mileage. Debris can enter the sump and block the oil pickup strainer, restricting oil flow to the pump and causing low oil pressure, serious engine damage and potentially complete engine failure. With over 754,000 vehicles on UK roads, this represents a significant aftermarket repair opportunity. BGA's LP2307 Oil Pump provides workshops with a reliable, OE-quality replacement solution for this high-demand application.



UPGRADE TO BGA

MOST POPULAR APPLICATIONS

MODEL	ENG. SIZE	FROM	TO
Fiesta	1.0	2012	->
Focus	1.0	2012	2025
B-Max	1.0	2012	2017
Transit Connect	1.0	2013	->

