













TECHNICAL BULLETIN

INSPECTION PRIOR TO INSTALLATION

TB-TC2312K-280324

TC2312K

	INLET CAMSHAFT (WITH BEARING)	EXHAUST (WITHOUT BEARING)
NEW TOOTH PROFILE	 <p>TOOTH CROWN</p> <p>LEADING FACE</p> <p>TOOTH PROFILE</p> <p>CS1414</p> <p>✓</p>	 <p>CS1415</p> <p>✓</p>
WORN TOOTH PROFILE	 <p>WORN PROFILE</p> <p>✗</p>	 <p>✗</p>
IMPORTANT	<p> Replace camshafts if signs of wear are evident.</p> <p> Ersetzen Sie die Nockenwelle, wenn Anzeichen von Verschleiß erkennbar sind.</p> <p> Remplacez l'arbre à cames si des signes d'usure sont évidents.</p>	<p> Sostituire l'albero a camme se sono evidenti segni di usura.</p> <p> Reemplace el árbol de levas si hay signos evidentes de desgaste.</p> <p> Замените распределительный вал, если очевидны признаки износа.</p>