




YOU REQUESTED, WE DELIVERED.

PRE BUILT DV5 KIT CS2340FK



FATIGUE FRACTURE



WORN PROFILE



OE 7MM PROBLEM:

Modern engines like the PSA DV5 are equipped with EGR and DPF systems improving MPG and lowering emissions. This leads to harmful soot accumulation, causing premature wear on critical components such as the timing chain and camshafts.

BGA 8MM SOLUTION:

To combat premature wear of the Timing Chain and Camshaft, OE and BGA have upgraded these components by increasing the chain pitch from 7mm to 8mm, along with modified camshafts and a camshafts carrier.



CS2340FK

KIT CONTENTS:


- CS14003 (8mm) - Camshaft
- CS14004 (8mm) - Camshaft
- TC2335K (8mm) - Timing Chain Kit
- CS1414B - Camshaft Bolt
- OS6703 - Oil Seal
- RK1406 - Gasket
- BGSILC - Silicone Sealant
- RC1421 - Camshaft Carrier 8mm

ASSEMBLED VERSION

IDENTIFYING A DV5 ENGINE 7MM OR 8MM TIMING SETUP.



#BESTUNDERPRESSURE
ENGINEERED
IN GREAT BRITAIN



TOP 10 VEHICLES WITH THE DV5 ENGINE

TOTAL
VEHICLES ON
THE UK ROADS
2025

MAKE	MODEL	FROM	TO	FUEL TYPE	LITRE	CYL	VALVES	ENGINE-CODE	MODEL-CODE	TOTAL VEHICLES ON THE UK ROADS 2025
VAUXHALL	VIVARO	2019	->	DIESEL	1.5	4	16	D15DT (DV5RUCD)	K0	33,173
VAUXHALL	COMBO	2018	->	DIESEL	1.5	4	16	D15DT (DV5RCF, DV5RD)	K9	29,211
PEUGEOT	PARTNER	2019	->	DIESEL	1.5	4	16	DV5RCF, DV5RD	E_YHT,E_YHY	25,675
PEUGEOT	3008	2018	->	DIESEL	1.5	4	16	DV5RC	MCYHZJ,MCYHZR	24,235
CITROEN	BERLINGO	2018	->	DIESEL	1.5	4	16	DV5RCF, DV5RD	E_YHT,E_YHY	22,266
CITROEN	BERLINGO	2019	->	DIESEL	1.5	4	16	DV5RE	E_YHW	12,981
PEUGEOT	5008	2017	->	DIESEL	1.5	4	16	DV5RC	MCYHZJ,MCYHZR	11,274
PEUGEOT	EXPERT	2018	->	DIESEL	1.5	4	16	DV5RUCD	V_YHR	9,880
VAUXHALL	GRANDLAND X	2018	2021	DIESEL	1.5	4	16	D15DTH (DV5RC)	75	9,702
CITROEN	DISPATCH	2018	->	DIESEL	1.5	4	16	DV5RUCD	V_YHR	9,394

THE BGA SOLUTIONS

UPGRADE & REBUILD KITS

CS2335FK & CS2336FK,
the most comprehensive
7mm -> 8mm upgrade
and rebuild.



CS2340FK

8MM UPGRADE KIT

KIT CONTENTS:
CS14003 (8mm) - Camshaft
CS14004 (8mm) - Camshaft
TC2335K (8mm) - Timing Chain Kit
CS1414B - Camshaft Bolt
OS6703 - Oil Seal
RK1406 - Gasket
BGSILC - Silicone Sealant
RC1421 - Camshaft Carrier 8mm



CS2336FK

8MM REBUILD KIT

KIT CONTENTS:
CS2335FK KIT CONTENTS PLUS:
BK3339 - Cylinder Head Bolts
HL1435 (x16) - Hydraulic Lifters
RA1435 (x16) - Rocker Arms
V203632 (x8) - Inlet Valves
V203633 (x8) - Exhaust Valves