

C09611

Oil Separator for VW 1.5 TSi engines

The PCV valve and the diaphragm are known to fail which means unmetered air is allowed into the intake, disrupting the fuel-air mixture and causing a loss of power, a hissing sound or the check engine light comes on. As this is a common failure, BGA have launched the entire separator to offer garages the complete solution.

UPGRADE TO BGA



MOST POPULAR APPLICATIONS

MAKE	MODEL	ENG. SIZE	FROM	TO
Audi	A1	1.5	2022	->
Cupra	Formentor	1.5	2022	->
Seat	Leon	1.5	2018	->
Skoda	Octavia	1.5	2019	->
VW	Golf	1.5	2020	->

GUARANTEED
ORIGINAL
QUALITY

